



IBS Maintenance Sheet

Care & Maintenance of IBS PanelLine Brace

IBS PanelLine Brace shouldn't require specific maintenance, provided the panels are protected from internal moisture.

If the panels have been painted then a general recoating will be required approximately every 5 years, or as the need arises. This may depend on the surface coating applied and the supplier's recommendations.

We also recommend regular inspections to check the sheets are not being damaged by humidity or moisture – particularly in buildings which are left mostly unheated. If you do find any evidence of swelling at the edge of the bracing panels, they must be removed and replaced with new ones.

Small holes (up to 90mm x 90mm) can be repaired by patching or stopping with a suitable interior grade filler.

If the holes are larger than 90mm square, or within 90mm of any bracing element seek advice from a Licensed Building Professional.

Similarly, if the bracing elements themselves are damaged, seek advice from a Licensed Building Professional.



USEFUL LINKS

For information on the design and specification of IBS PanelLine Brace, refer to:

|| [IBS PanelLine Brace Design & Installation Guide](#)

For information to help install PanelLine Brace, refer to:

|| [IBS PanelLine Brace Design & Installation Guide](#)

For our warranty on IBS supplied PanelLine Brace refer to:

|| [IBS PanelLine Brace Warranty](#)



ABOUT IBS

Independent Building Supplies (IBS) has been distributing panel products around New Zealand since 1993. Our focus is on sourcing the best panel products available from around the world from sustainable renewable resources. IBS products are supported by full technical literature and support providing our customers with the **Best Products**, the **Best Service**, and the **Best Experience**.